

Conversion Chart



| INCHES | INCHES DECIMAL | MILLIMETERS |
|--------|----------------|-------------|
| 1/64 | .0156 | 0.397 |
| 1/32 | .0313 | 0.794 |
| 3/64 | .0469 | 1.191 |
| 1/16 | .0625 | 1.588 |
| 5/64 | .0781 | 1.984 |
| 3/32 | .0938 | 2.381 |
| 7/64 | .1094 | 2.778 |
| 1/8 | .1250 | 3.175 |
| 9/64 | .1406 | 3.572 |
| 5/32 | .1563 | 3.969 |
| 11/64 | .1719 | 4.366 |
| 3/16 | .1875 | 4.763 |
| 13/64 | .2031 | 5.159 |
| 7/32 | .2188 | 5.556 |
| 15/64 | .2344 | 5.953 |
| 1/4 | .2500 | 6.350 |
| 17/64 | .2656 | 6.747 |
| 9/32 | .2813 | 7.144 |
| 19/64 | .2969 | 7.541 |
| 5/16 | .3125 | 7.938 |
| 21/64 | .3281 | 8.334 |
| 11/32 | .3438 | 8.731 |
| 23/64 | .3594 | 9.128 |
| 3/8 | .3750 | 9.525 |
| 25/64 | .3906 | 9.922 |
| 13/32 | .4063 | 10.319 |
| 27/64 | .4219 | 10.716 |
| 7/16 | .4375 | 11.113 |
| 29/64 | .4531 | 11.509 |
| 15/32 | .4688 | 11.906 |
| 31/64 | .4844 | 12.303 |
| 1/2 | .5000 | 12.700 |
| 33/64 | .5156 | 13.097 |
| 17/32 | .5313 | 13.494 |
| 35/64 | .5469 | 13.891 |
| 9/16 | .5625 | 14.288 |
| 37/64 | .5781 | 14.684 |
| 19/32 | .5938 | 15.081 |
| 39/64 | .6094 | 15.478 |
| 5/8 | .6250 | 15.875 |

| INCHES | INCHES DECIMAL | MILLIMETERS |
|--------|----------------|-------------|
| 41/64 | .6406 | 16.272 |
| 21/32 | .6563 | 16.669 |
| 43/64 | .6719 | 17.066 |
| 11/16 | .6875 | 17.463 |
| 45/64 | .7031 | 17.859 |
| 23/32 | .7188 | 18.256 |
| 47/64 | .7344 | 18.653 |
| 3/4 | .7500 | 19.050 |
| 49/64 | .7656 | 19.447 |
| 25/32 | .7813 | 19.844 |
| 51/64 | .7969 | 20.241 |
| 13/16 | .8125 | 20.638 |
| 53/64 | .8281 | 21.034 |
| 27/32 | .8438 | 21.431 |
| 55/64 | .8594 | 21.828 |
| 7/8 | .8750 | 22.225 |
| 57/64 | .8906 | 22.622 |
| 29/32 | .9063 | 23.019 |
| 59/64 | .9219 | 23.416 |
| 15/16 | .9375 | 23.813 |
| 61/64 | .9531 | 24.209 |
| 31/32 | .9688 | 24.606 |
| 63/64 | .9844 | 25.003 |
| 1 | 1.0000 | 25.400 |
| 2 | 2.0000 | 50.800 |
| 3 | 3.0000 | 76.200 |
| 4 | 4.0000 | 101.600 |
| 5 | 5.0000 | 127.000 |
| 6 | 6.0000 | 152.400 |
| 7 | 7.0000 | 177.800 |
| 8 | 8.0000 | 203.200 |
| 9 | 9.0000 | 228.600 |
| 10 | 10.0000 | 254.000 |
| 11 | 11.0000 | 279.400 |
| 12 | 12.0000 | 304.800 |
| 13 | 13.0000 | 330.200 |
| 14 | 14.0000 | 355.600 |
| 15 | 15.0000 | 381.000 |
| 16 | 16.0000 | 406.400 |
| 17 | 17.0000 | 431.800 |

To convert pounds to kilograms use the following formula:
 Kilograms = Pounds ÷ 2.2046